

# W30

The diagram illustrates the assembly of the W30 coat rack in seven steps:

- Step 1:** Attaching the top cap (B) to the central post (C) using screws (K). 80% completion.
- Step 2:** Attaching the top ring (F) to the central post (C) using screws (K). 80% completion.
- Step 3:** Attaching the top ring (F) to the central post (C) using screws (K). 100% completion.
- Step 4:** Attaching the side arms (A) to the central post (C) using screws (J). 80% completion.
- Step 5:** Attaching the side arms (A) to the central post (C) using screws (J). 80% completion.
- Step 6:** Attaching the side arms (A) to the central post (C) using screws (J). 100% completion.
- Step 7:** Final assembly showing the complete coat rack with a height of 188 cm and a width of 49 cm. It has a maximum weight capacity of 15 kg.

**Parts List:**

A		4	G		1
B		1	H		1
C		1	I		6
D		1	J		8
E		1	K		20
F		1	L		4

HALMAR Sp. z o.o.  
 ul. Centralnego Okręgu Przemysłowego 2, 37-450 Stalowa Wola, POLSKA / POLAND  
 tel. +48 15 843 28 10, fax: +48 15 842 19 57, e-mail: office@halmar.com.pl