

**W53**

The diagram illustrates the assembly of a coat rack in four steps:

- 1**: Identification of components: A (base plate), B (main pole), C (branch pole), D (base cap), E (branches), F (pole connector), G (nut), and H (washer).
- 2**: Attaching the base cap (D) to the main pole (B) using the pole connector (F) and nut (G).
- 3**: Attaching the branch pole (C) to the main pole (B) using the pole connector (F) and nut (G).
- 4**: Final assembly with branches (E) attached to the branch pole (C).

A		1
B		1
C		1
D		1
E		6
F	 M8 x 50MM	1
G	 M8 x 35MM	1
H		1

Dimensions: 170 cm (height), 35 cm (base diameter)

v.1

HALMAR Sp. z o.o.  
 ul. Centralnego Okręgu Przemysłowego 2, 37-450 Stalowa Wola, POLSKA / POLAND  
 tel. +48 15 843 28 10, fax: +48 15 842 19 57, e-mail: office@halmar.com.pl