

H-64

The assembly diagram consists of six numbered steps:

- Step 1: Shows the seat (A) and the base plate (J) with legs (I) attached.
- Step 2: Shows the seat (A) being placed on top of the base plate (J) and secured with a cap (G).
- Step 3: Shows the four legs (E) being attached to the base plate (J) using a bracket (D).
- Step 4: Shows the legs (E) being secured to the base plate (J) with screws (G).
- Step 5: Shows the base plate (J) being secured to the legs (E) with screws (H).
- Step 6: Shows the final assembled stool with the seat (A) and base plate (J) in place.

The parts list is as follows:

A		1
B		1
C		1
D		1
E		4
F		1
G		12
H		4
I		4
J		1

Technical specifications:

- max. 120 kg
- 30 cm (width)
- 63-80 cm (height)

AI_v2_mod_20160824

HALMAR Sp. z o.o.
 ul. Centralnego Okręgu Przemysłowego 2, 37-450 Stalowa Wola, POLSKA / POLAND
 tel. +48 15 843 28 10, fax: +48 15 842 19 57, e-mail: office@halmar.com.pl